

18
WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
and Enforcement Branch (31.62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1-4-17

Operator Project No: 064-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>		
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>		
Facility Owner: Name: Walter Osborne Address: P.O. Box 2139 City: Fairmont State: WV Zip Code: 26555 Contact Person: Walter Osborne Phone: (304) 290-1591		
Facility Description: Name: Former CVS building Address: 1201 Beverly Road City: Fairmont County: Marion County Location Within Facility: Interior/ exterior Building Size (Sq. Ft.): 11,500 Number of Floors: 2 Age (Yrs): 40+ Present Use: Vacant Prior Use: CVS Store		
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070		
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070		
Building Inspection: Inspection Date: 7-19-2016 Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Mikaela Batta Procedure Used to Detect Presence of Asbestos: PLM Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509		
Schedule: Asbestos Removal: Start Date: 1-19-17 Completion Date: 2-19-17 Demo/Renovation: Start Date: 2-20-17 Completion Date: 3-20-17 Project Work Hours: 7am-5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input type="checkbox"/> Su <input type="checkbox"/> (Check)		

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: WV042918

State: WV


Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 1 / 4 / 17

Name and Title (Print or Type): Drew Nieman, Assistant Project Manager



Demolition of Former CVS

Lab ID	ASBESTOS TO BE REMOVED	APPROX. SIZE	Amosite	CHRYSTILE	INSPECTION DATE	INSPECTOR	ANALYST
15	White pipe wrap insulation	250LF	5%	10%	7/19/2016	Jason Frazier A1008690	Mikaela Batta
16	Gray pipe wrap insulation			65%	7/19/2016		
17	White pipe wrap insulation		5%	10%	7/19/2016		
18	White pipe wrap insulation	90LF	5%	10%	7/19/2016		
19	White pipe wrap insulation		5%	10%	7/19/2016		
20	White pipe wrap insulation		5%	10%	7/19/2016		
21	Green floor tile	240SF		10%	7/19/2016		
	Black Mastic			3%	7/19/2016		
22	Green floor tile			10%	7/19/2016		
	Black Mastic			3%	7/19/2016		
25	Black built-up roofing	4896SF		2%	7/19/2016		
26	Black built-up roofing			2%	7/19/2016		
27	Black built-up roofing			2%	7/19/2016		

WEST VIRGINIA


 RECEIVED
 JAN 09 2017

 Pesticides & Asbestos Programs
 and Enforcement Branch (SLC62)
 EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:	Check No:
Postmark Date:	Paid By:
Notification No:	Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 8A (Kanawha County) Address: City: Location Within Facility: County: Number of Floors: Age (Yrs): Building Size (Sq. Ft.): Prior Use: Present Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: <u>Harold Rumer</u> WV License #: <u>AD003820</u> Air Monitor: <u>Harold Rumer</u> WV License #: <u>AD002509</u>	
Schedule: Asbestos Removal: Start Date: 12/14/2016 Completion Date: 02/28/17 Demo/Renovation: Start Date: 12/14/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 1 04 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 8

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTOR	INSPECTION DATE	ANALYST	COMPLETE
K-1	2 Welford Hollow Road, Clendenin	38.53071, -81.33895	Flashing around windows	84 LF	Assumed	J. Sommers AI008854	12/8/2016	Scott Minyard	X
K-22	5639 Little Blue Creek, Clendenin	38.52631, -81.30578	Flashing around chimney	25 LF	Assumed	J. Sommers AI008854	12/8/2016	Daniel Liguori	X
K-44	4215 Thorofare Road, Clendenin	38.52753, -81.31513	Black Adhesive around roof vents	15 LF	Assumed	J. Frazier AI008690	12/8/2016	Daniel Liguori	X
K-102	4825 Thorofare Road, Clendenin	38.52942, -81.30864	Linoleum	6 SF	Assumed	J. Frazier AI008690	12/15/2016	Taylor B. Metcalf	

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
and Environmental Health (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 7A (Kanawha County) Address: City: County: Location Within Facility: Building Size (Sq. Ft.): Number of Floors: Age (Yrs): Present Use: Prior Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: <u>Harold Rumer</u> WV License #: <u>AD002509</u>	
Schedule: Asbestos Removal: Start Date: 12/19/2016 Completion Date: 02/28/17 Demo/Renovation: Start Date: 12/19/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV


Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 1/04/17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 7

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTOR	INSPECTION DATE	ANALYST	COMPLETE
K-124	1971 River Haven Road, Clendenin	38.48111, -81.28495	Black Tar on Roof Vent	UK	Assumed	J. Frazier AI008690	12/13/2016	Sarah Talley	
K-85	44 Marburg Road, Clendenin	38.49802, -81.3482	Silver Paint	840 SF	3%	J. Frazier AI008690	12/13/2016	Shilpa Ladekar	
			Black Adhesive on Roof Vents	5 SF	Assumed				
K-82	1485 Spencer Road, Clendenin	38.50116, -81.34876	Glazing on door windows	20 LF	Assumed	J. Frazier AI008690	12/13/2016	Sarah Talley	
K-33	3555 River Haven Road, Clendenin	38.48167, -81.26496	Brown Linoleum	32 SF	Assumed	J. Sommers AI008854	12/8/2016	Daniel Liguori	X
K-81	51 Elk River Road, Clendednin	38.48452, -81.36013	Gray Floor Tile	468 SF	5%	J. Frazier AI008690	12/13/2016	Candace Burrus	
			Brown Floor Tile	468 SF	5%				
			Tan Floor Tile	48 SF	2%				
			Window Glazing	50 LF	Assumed			Daniel Liguori	
K-81 (A1)			Transite Siding	2000 SF	15%				
			Chimney Mastic	5 LF	Assumed				
K-81 (A2)			Window Glazing	10 LF	Assumed			Daniel Liguori	
K-81 (A3)			None Detected	N/A	N/A			Daniel Liguori	
K-81 (A4)	9"x9" Floor Tile	25 SF	Assumed	Candace Burrus					
K-13	103-1/2 Cobb Avenue, Clendenin	38.4929, -81.35035	Silver/Black Paint	900 SF	3%	J. Sommers AI008854	12/8/2016	Scott Minyard	X
			Shingles	12 SF	Assumed				
K-39	40 Spencer Avenue, Clendenin	38.4816, -81.365458	Black Tar on Weatherhead	2 LF	Assumed	J. Frazier AI008690	12/12/2016	Sarah Talley	
K-40	606 Spencer Road, Clendenin	38.49152, -81.35083	Mastic from Heater	3 LF	Assumed	J. Sommers AI008854	12/8/2016	Anna Malmberg	X
K-41	927 Spencer Road, Clendenin	38.49501, -81.35314							
K-42	1000 Spencer Road, Clendenin	38.49556, -81.35184	Silver/Black Paint	470 SF	3%	J. Sommers AI008854	12/8/2016	Scott Minyard	X
K-7	1 Bethmont Drive, Clendenin	38.51194, -81.55083	Mastic around roof vents	5 LF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	X
K-8	52 Big Sandy Avenue, Clendenin	38.50503, -81.3513	Mastic on roof vents	5 LF	Assumed	J. Sommers AI008854	12/8/2016	Megan Fisher	X
K-10	126 Big Sandy Avenue, Clendenin	38.50643, -81.35359	Window Glazing	24 LF	Assumed	J. Sommers AI008854	12/8/2016	Daniel Liguori	X
K-11	170 Bid Sandy Avenue, Clendenin	38.50669, -81.35425	Wiring	UK	Assumed	J. Sommers AI008854	12/8/2016	Anna Malmberg	X
K-9	403 Big Sandy Avenue, Clendenin	38.50824, -81.35809	Wiring	UK	Assumed	J. Sommers AI008854	12/8/2016	Anna Malmberg	X
K-43	1994 Spencer Road, Clendenin	38.50578, -81.35541	9"x9" Floor Tile	18 SF	Assumed	J. Frazier AI008690	12/8/2016	Anna Malmberg	X
K-28	9 Portland Drive, Clendenin	38.50576, -81.3558	Window Glazing	36 LF	Assumed	J. Frazier AI008690	12/8/2016	Ryan Williams	X
K-29	17 Portland Drive, Clendenin	38.505916, -81.355845	Off-White/Green Linoleum	UK - Debris on top	25%	J. Frazier AI008690	12/8/2016	Ryan Williams	X
			Gray Transite	UK - Debris on top	15%				
			Silver Metal Roofing (paint/tar)	UK - Smashed	3%				
			Window Glazing	UK - Mixed throughout	Assumed				
K-109	35 Symphony Dr., Clendenin	38.51094, -81.35688	Black Tar on Roof Vents	5 SF	Assumed	J. Frazier AI008690	12/16/2016	Taylor B. Metcalf	

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
(C62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 6A (Kanawha County) Address: _____ City: _____ County: _____ Location Within Facility: _____ Building Size (Sq. Ft.): _____ Number of Floors: _____ Age (Yrs): _____ Present Use: _____ Prior Use: _____	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule: Asbestos Removal: Start Date: 12/20/2016 Completion Date: 02/28/17 Demo/Renovation: Start Date: 12/20/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV


Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 01/04/17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 6

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTOR	INSPECTION DATE	ANALYST	COMPLETE
K-25	306 Maywood Drive, Clendenin	38.48730, -81.35205	Mastic around roof vent	4 LF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	X
K-24	110 Maywood Avenue, Clendenin	38.48825, -81.34988	Linoleum	12 SF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	X
K-20	214 Koontz Avenue, Clendenin	38.489924, -81.34357	Wiring in house	100 LF	Assumed	J. Sommers AI008854	12/7/2016	Scott Minyard	X
K-14	202 Elk Avenue, Elkview	38.48844, -81.35105							
K-27	5 Pleasant Street, Clendenin	38.48784, -81.35135	Mastic around roof vent	5 LF	Assumed	J. Sommers AI008854	12/7/2016	Anna Malmberg	
K-80	110 Koontz Avenue, Clendenin		Transite Siding	800 SF	15%	J. Frazier AI008690	12/13/2016	Sarah Talley	
			Floor Tile	150 SF	Assumed				

WEST VIRGINIA



R E C E I V E D
JAN 09 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:	Check No:
Postmark Date:	Paid By:
Notification No:	Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 5A (Kanawha County) Address: City: Location Within Facility: County: Number of Floors: Age (Yrs): Building Size (Sq. Ft.): Prior Use: Present Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: <u>Harold Rumer</u> WV License #: <u>AA002509</u>	
Schedule: Asbestos Removal: Start Date: 12/19/2016 Completion Date: 1-4-17 Demo/Renovation: Start Date: 12/19/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV

Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: _____

Date: 1/04/17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



**WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 5**

ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	ANALYST
K-23	643-1/2 Maywood Avenue, Clendenin	38.49033, -81.33366	Window Glazing	72 LF	Assumed	12/6/2016	Salthya Painkal
K-26	722 Maywood Avenue West, Clendenin	38.48317, -81.35935	Black Tar	2 LF	Assumed	12/9/2016	Mikaela Batta
K-32	874 Reamer Road, Clendenin	38.48172, -81.36189	Linoleum	100 SF	Assumed	12/6/2016	Salthya Painkal
K-35	51 Salmon Lane, Clendenin	38.47803, -81.36962	Beige Floor Tile	140 SF	3%	12/6/2016	Scott Minyard
			Off-White Floor Tile	150 SF	5%		
			9"x9" Floor Tile	60 SF	Assumed		
K-12	259 Brown Street, Clendenin	38.4772, -81.37012	Window Glazing	112 LF	Assumed	12/6/2016	Salthya Painkal
K-30	28 Rawhide Drive, Clendenin	38.476493, -81.37169	Linoleum	10 SF	Assumed	12/6/2016	Salthya Painkal
K-31	72 Rawhide Drive, Clendenin	38.47686, -81.37139	Chimney Mastic	8 SF	Assumed	12/7/2016	Scott Minyard
K-34	58 Rosewater Lane, Clendenin	38.47547, -81.37269	Black Adhesive around roof vents	52 SF	Assumed	12/7/2016	Daniel Liguori
K-36	30 Sigma Drive, Clendenin	38.47345, -81.37841	Chimney Mastic	10 LF	Assumed	12/7/2016	Scott Minyard
K-37	134 Sigma Drive, Clendenin	38.47339, -81.379389	Beige 12"x12" Self Stick Tile	120 SF	2%	12/7/2016	Salthya Painkal
			Beige 12"x12" Self Stick Tile	44 SF	2%		
			9"x9" Floor Tile	100 SF	Assumed		
K-38	146 Sigma Drive, Clendenin	38.28241, -81.22437	Linoleum	56 SF	Assumed	12/7/2016	Salthya Painkal
K-46	504 Youngstown Drive, Clendenin	38.47272, -81.38926	None Detected	N/A	N/A	12/7/2016	Salthya Painkal

WEST VIRGINIA


 RECEIVED
 JAN 09 2017

 Pesticides & Asbestos Programs
 and Enforcement Branch (3LC62)

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:	Check No:
Postmark Date:	Paid By:
Notification No:	Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 4A (Kanawha County) Address: City: Location Within Facility: County: Number of Floors: Age (Yrs): Building Size (Sq. Ft.): Prior Use: Present Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule: Asbestos Removal: Start Date: 12/09/2016 Completion Date: 2-28-17 Demo/Renovation: Start Date: 12/09/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



**WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 4**

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	ANALYST	COMPLETE
K-53	5538 Elk River Road, Elkview	38.46992, -81.4005	Linoleum	5 SF	Assumed	12/2/2016	Shilpa Ladekar	X
K-18	1444 Jordan Creek Road, Elkview	38.47775, -81.39781	Silver Paint	600 SF	2%	12/2/2016	Shilpa Ladekar	X
			Linoleum	100 SF	Assumed			
K-3	2007 Jordan Creek Road, Elkview	38.48288, -81.38996	Silver Paint on Roof	600 SF	Assumed	12/2/2016	Shilpa Ladekar	X
			Linoleum	UK (no access)	Assumed			
K-65	31 Strawberry Path Lane, Clendenin	38.4729, -81.39635	Window Glazing	64 LF	2%	12/2/2016	Salthya Painkal	X
			Floor Tile	2 SF	Assumed			
K-66	61 Strawberry Path Lane, Clendenin	38.2821, -81.2350	Black Tar (back porch roof)	5 LF	Assumed	12/2/2016	Candace Burrus	X
K-45	102 Wall Street, Clendenin	38.28958, -81.21892	Linoleum	170 SF	25%	12/5/2016	Shilpa Ladekar	X
			Floor Tile	144 SF	25%			
			Black Tar	2 LF	Assumed			
K-89	5 Chandler Lane, Clendenin	38.48024, -81.36804	Linoleum	45 SF	Assumed	12/14/2016	Shilpa Ladekar	
K-19	120 Kelly Avenue, Clendenin	38.4816, -81.365158	Black Tar on roof vent	3 SF	Assumed	12/5/2016	Shilpa Ladekar	X
K-17	301 S. Elk River Road, Clendenin	38.48411, -81.36026	Black Tar	4 LF	Assumed	12/2/2016	Sarah Talley	X
K-16	47 S. Elk River Road, Clendenin	38.48457, -81.35962	Brown Floor Tile	900 SF	5%	12/5/2016	Sarah Talley	X
			White Floor Tile	900 SF	2%			
			Window Caulking	144 LF	5%			
			Window Glazing	20 LF	Assumed			
			Pipe Wrap	60 LF	Assumed			
K-15	27 S. Elk River Road, Clendenin	38.52611, -81.47361	Exterior Caulking on gutter	6 LF	Assumed	12/5/2016	Salthya Painkal	X

WEST VIRGINIA



R E C E I V E D
JAN 09 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
Sales Enforcement Branch (SLC62)
EPA Region III

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:	Check No:
Postmark Date:	Paid By:
Notification No:	Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 3A (Kanawha County) Address: City: Location Within Facility: County: Number of Floors: Age (Yrs): Building Size (Sq. Ft.): Prior Use: Present Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Jason Frazier WV License #: AI008690 Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule: Asbestos Removal: Start Date: 12/09/2016 Completion Date: 2-28-17 Demo/Renovation: Start Date: 12/09/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV


Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 3

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTION DATE	ANALYST	COMPLETE
K-84	29 Darlington Lane, Elkview	38.46006, -81.44979	Silver Paint on Roof	660 SF	3%	11/21/2016	Samantha Card	
			Black Tar - Roof Vents	10 LF	Assumed			
			Linoleum	200 SF	Assumed			
K-73	11 Weeping Willow Lane, Elkview	38.46103, -81.44855	Silver Paint	650 SF	10%	11/23/2016	Sarah Talley	X
			Caulking around Door	22 LF	Assumed			
K-74	16 Weeping Willow Lane, Elkview	38.46122, -81.44843	Black Tar on Roof	26 LF	Assumed	11/23/2016	Taylor B. Metcalf	X
K-75	32 Weeping Willow Lane, Elkview	38.46100, -81.44814	Window Glazing	20 LF	Assumed	11/23/2016	Sarah Talley	X
K-76	36 Weeping Willow Lane, Elkview	38.46115, -81.44827	Linoleum	250 SF	Assumed	11/23/2016	Shilpa Ladekar	X
K-50	5226 Elk River Road N., Elkview	38.4614, -81.44831	Window Glazing	64 LF	Assumed	11/23/2016	Sarah Talley	X
K-79	34 Knight Lane, Elkview	38.46155, -81.44771	Linoleum	134 SF	Assumed	11/23/2016	Saithya Painkal	
K-61	36 Knight Lane, Elkview	38.46194, -81.44740	Linoleum	45 SF	Assumed	11/23/2016	Saithya Painkal	X
K-62	36A Knight Lane, Elkview	38.46194, -81.4475	Window Glazing	60 LF	Assumed	11/23/2016	Saithya Painkal	X
K-57	70 Iceberg Drive, Elkview	38.46205, -81.44721	Tar around Roof Hood	5 LF	Assumed	11/23/2016	Taylor B. Metcalf	X
K-86	24 Dixie Street, Elkview	38.46343, -81.44607	Black Tar around perimeter of roof	162 LF	Assumed	12/12/2016	Daniel Liguori	
K-51	5292 Elk River Road, Elkview	38.46668, -81.437244	Silver Paint/Roof	770 SF	2%	11/23/2016	Saithya Painkal	X
			Black Tar on Roof	15 LF	Assumed			X
K-78	5290 Elk River Road, Elkview	38.4667, -81.4376	White/Silver Roof Paint	720 SF	2%	11/23/2016	Shilpa Ladekar	
			Linoleum	20 SF	Assumed			
K-54	5294 Elk River Road N., Elkview	38.46665, -81.43687	Roof Paint	780 SF	5%	11/23/2016	Megan Rumble	X
			Tar on Roof	170 LF	Assumed			
K-52	5312 Elk River Road, Elkview	38.46552, -81.43262	Window Glazing	120 LF	Assumed	11/23/2016	Ritika Seal	X
K-59	38 John Edward Lane, Elkview	38.46584, -81.42957	Black Tar	5 SF	Assumed	11/29/2016	Taylor B. Metcalf	X
K-60	54 John Edward Lane, Elkview	38.4659, -81.42993	Black Tar	5 SF	Assumed	11/29/2016	Taylor B. Metcalf	X
K-83	35 Cassell Drive, Elkview	38.4635, -81.34042	None Detected	N/A	N/A	12/12/2016	Candace Burrus	
K-125	12 John Edward Lane, Elkview	38.46514, -81.42993	Black Tar around Porch Roof	10 LF	Assumed	12/13/2016	Sarah Talley	

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒

Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 2A (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002330

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Harold Rumer

WV License #: AD003673 3820

Air Monitor: Harold Rumer

WV License #: AA002445 2509

Schedule:

Asbestos Removal:

Start Date: 11/30/2016

Completion Date: 2-28-17

Demo/Renovation:

Start Date: 11/30/2016

Completion Date: 02/28/2017

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: Angela MitchellDate: 1 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 2

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	ANALYST	COMPLETE
K-63	80 Narrow Branch Road, Elkview	38.44812, -81.46625	None Detected	N/A	N/A	11/21/2016	Samantha Card	X
K-64	82 Narrow Branch Road, Elkview	38.44803, -81.46652	Linoleum	100 SF	Assumed	11/21/2016	Samantha Card	X
K-58	778 Islandview Road, Elkview	38.44268, -81.4665	None Detected	N/A	N/A	11/18/2016	Taylor Metcalf	X
K-67	985 Walgrove Road, Elkview	38.45492, -81.45061	Silver Paint (roof)	672 SF	Assumed	11/18/2016	Assumed	X
K-68	1019 Walgrove Road, Elkview	38.45505, -81.45018	Roofing Material	858 SF	Assumed	11/19/2016	Candace Burns	X
			Linoleum	200 SF	25%			
K-69	1037 Walgrove Road, Elkview	38.45529, -81.45063	Floor Tile	28 SF	Assumed	11/18/2016	Megan Fisher	X
			Silver Paint on Roof	200 SF	Assumed			
K-70	1039 Walgrove Road, Elkview	38.4552, -81.45045	Linoleum	180 SF	Assumed	11/21/2016	Samantha Card	X
K-71	1149 Walgrove Road, Elkview	38.45661, -81.44899	Silver Paint	660 SF	2%	11/21/2016	Samantha Card	X
			Linoleum	40 SF	Assumed			
K-72	1517 Walgrove Road, Elkview	38.46121, -81.445987	Window Caulking	20 LF	Assumed	11/21/2016	Taylor Metcalf	X
K-111	1473 Walgrove Road, Elkview	38.46099, -81.44632	Silver Paint	600 SF	3%	12/15/2016	Taylor Metcalf	
			Black Tar on Roof Vents	5 SF	Assumed			
K-112	1459 Walgrove Road, Elkview	38.46062, -81.44671	Linoleum (middle of trailer)	100 SF	Assumed	12/16/2016	Megan Rumble	

WEST VIRGINIA


 RECEIVED
 JAN 09 2017

 Pesticides & Asbestos Programs
 and Enforcement Branch (3LC62)
 EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:	Check No:
Postmark Date:	Paid By:
Notification No:	Amount: \$

Type of Notification:

Original ☒Revision ☐ (Highlight Changes)Cancellation ☐

Type of Operation:

Demolition ☒Ordered Demolition ☐Renovation ☐Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 1A (Kanawha County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002330

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Jason Frazier

WV License #: AI008690

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Harold Rumer

WV License #: AD003820

Air Monitor: Harold Rumer

WV License #: AA002509

Schedule:

Asbestos Removal:

Start Date: 11/30/2016

Completion Date: 2-28-17

Demo/Renovation:

Start Date: 11/30/2016

Completion Date: 02/28/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330


Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Kanawha County, WV - Group 1

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	ANALYST	COMPLETE
K-126	56 Harlech Lane, Elkview	38.40892, -81.51071	Linoleum	20 SF	Assumed	12/12/2016	Sarah Talley	
K-2	40 Benthaven Lane, Elkview	38.428593, -81.515804	Window Glazing	32 LF	3%	11/17/2016	Anna Malmberg	X
K-47	416 Briarwood Road, Elkview	38.2543, -81.3026	Silver Paint	600 SF	2%	11/17/2016	Megan Fisher	X
K-48	430 Briarwood Road, Elkview	38.42838, -81.50705	None Detected	N/A	N/A	11/17/2016	Mikaela Batta	X
K-49	416 A Briarwood Road, Elkview	38.42859, -81.50787	Black/Silver Tar	638 SF	5%	11/17/2016	Anna Malmberg	X
			Silver Paint	638 SF	5%	11/17/2016		
			Black/Silver Paint	638 SF	2%	11/17/2016		
K-77	381 West Wood Drive, Elkview	38.41741, -81.504187	None Detected	N/A	N/A	11/17/2016	Megan Fisher	X
K-87	561-B Little Sandy Creek Road, Elkview	38.41842, -81.50396	Linoleum	30 SF	Assumed	11/21/2016	Taylor B. Metcalf	
K-55	3279 Frame Road, Elkview	38.46861, -81.499383	Silver/Black Caulking	10 LF	5%	11/17/2016	Anna Malmberg	X
K-56	3319 Frame Road, Elkview	38.469, -81.49932	Silver Paint on Roof	1260 SF	Assumed	11/18/2016	Taylor B. Metcalf	X
K-5	1788 Wills Creek Road, Elkview	38.2791, -81.29185	Black Tar on shingles	1280 SF	Assumed	11/19/2016	Mikaela Batta	X
K-4	29 Little Fork Road, Elkview	38.485903, -81.455825	Transite Siding	1900 SF	Assumed	11/18/2016	Samantha Card	X
K-6	5945 Wills Creek Road, Elkview	38.4884, -81.42901	Transite Siding	1200 SF	Assumed	11/18/2016	Samantha Card	X
			Black Tar	1500 SF	5%	11/18/2016		
			Black Tar	1500 SF	5%	11/18/2016		
			Window Glazing	70 LF	5%	11/18/2016		
			Window Glazing	70 LF	5%	11/18/2016		
K-127	3091 Frame Road, Elkview	38.46586, -81.49936	Black Tar - Roof Vents	20 SF	Assumed	12/12/2016	Daniel Liguori	
K-115	7369 Wills Creek Road, Elkview	38.50279, -81.41266	Linoleum in Bathroom	25 SF	Assumed	12/16/2016	Taylor B. Metcalf	

WEST VIRGINIA



R E C E I V E D
JAN 09 2017

Pesticides & Asbestos Programs
and Enforcement Branch (31C62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒

Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 1A (Greenbrier)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002330

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: Please see attached.

WV License #: Please see attached.

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Harold Rumer

WV License #: AD003820

Air Monitor: Harold Rumer

WV License #: AA002509

Schedule:

Asbestos Removal:

Start Date: 12/01/2016

Completion Date: 1-4-17

Demo/Renovation:

Start Date: 12/01/2016

Completion Date: 02/28/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: _____

Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



**WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 1**

ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-31	102 Crescent Avenue, White Sulphur Springs	37.79654, 80.29957	Linoleum	32 SF	Assumed	11/28/2016	J. Sommers AI008854	Samantha Card
G-32	202 Crescent Avenue, White Sulphur Springs	37.79769, 80.30034	Linoleum	32 SF	Assumed	11/28/2016	J. Sommers AI008854	Samantha Card
			Green/Brown Linoleum	200 SF	25%	11/28/2016	J. Sommers AI008854	Samantha Card
			Tan/Brown Linoleum	200 SF	25%	11/28/2016	J. Sommers AI008854	Samantha Card
			Siding	1200 SF	15%	11/28/2016	J. Sommers AI008854	Samantha Card
			Window Glazing	3 Windows	2%	11/28/2016	J. Sommers AI008854	Samantha Card
G-25	200 Central Avenue, White Sulphur Springs	37.79806, 80.30024	Black Tar on Chimney	5 LF	Assumed	11/28/2016	J. Sommers AI008854	Samantha Card
G-30	252 Central Avenue, White Sulphur Springs	37.79885, 80.30095	Floor Tile	50 SF	Assumed	11/28/2016	J. Sommers AI008854	Daniel Liguori
			Siding	1500 SF	15%			
G-27	429 Big Draft Road, White Sulphur Springs	37.798583, 80.301926	Black Mastic Roof Flashing	10 LF	Assumed	11/28/2016	J. Sommers AI008854	Daniel Liguori
G-28	474 Big Draft Road, White Sulphur Springs	37.79900, 80.30202	Linoleum	180 SF	Assumed	11/28/2016	J. Sommers AI008854	Shilpa Ladekar
			Black Tar	800 SF	5%			

WEST VIRGINIA



RECEIVED
JAN 09 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Participate in Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region III

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 2A (Greenbrier) Address: _____ City: _____ County: _____ Location Within Facility: _____ Building Size (Sq. Ft.): _____ Number of Floors: _____ Age (Yrs): _____ Present Use: _____ Prior Use: _____	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. Lab: CEI Labs WV License #: Please see attached. Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule: Asbestos Removal: Start Date: 12/08/2016 Completion Date: 1-4-17 Demo/Renovation: Start Date: 12/08/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ ___:___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV


Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



**WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 2**

ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-50	219 Ivy Street, White Sulphur Springs	37.803007, 80.300157	Gray Siding	150 SF	15%	11/28/2016	J. Sommers AI008854	Mikaela Batta
			12"x12" Floor Tile	30 SF	Assumed			
G-45	140 Ivy Street, White Sulphur Springs	37.80326, 80.29944	Linoleum	10 SF	Assumed	11/30/2016	J. Sommers AI008854	Mikaela Batta
G-47	158 Ivy Street, White Sulphur Springs	37.80317, 80.29958	Window Glazing	16 LF	2%	11/28/2016	J. Sommers AI008854	Samantha Card
			Black Mastick	4 LF	Assumed			
G-46	147 Ivy Street, White Sulphur Springs	37.80322, 80.29946	Linoleum	28 SF	Assumed	11/28/2016	J. Sommers AI008854	Samantha Card
G-48	159 Ivy Street, White Sulphur Springs	37.80307, 80.29958	Vinyl Flooring	32 SF	Assumed	11/28/2016	J. Sommers AI008854	Shilpa Ladekar
G-49	166 Ivy Street, White Sulphur Springs	37.80296, 80.29972	Mastic on Flashing	3 LF	Assumed	11/28/2016	J. Sommers AI008854	Samantha Card
G-44	135 Ivy Street, White Sulphur Springs	37.80332, 80.29940	Linoleum	60 SF	Assumed	11/28/2016	J. Sommers AI008854	Daniel Liguori
G-43	125 Ivy Street, White Sulphur Springs	37.803299, -80.299016	Block Insulation	5 SF	Assumed	11/28/2016	J. Sommers AI008854	Mikaela Batta
			Linoleum	150 SF	25%			
G-42	111 Ivy Street, White Sulphur Springs	37.803457, -80.298832	Black Mastick	140 LF	2%	11/30/2016	J. Sommers AI008854	Mikaela Batta
			Caulking	24 LF	Assumed			
G-52	211 Maple Avenue, White Sulphur Springs	37.80364, 80.29882	Kitchen VCT	32 SF	Assumed	11/30/2016	J. Sommers AI008854	Candace Burrus
G-1	222 Maple Avenue, White Sulphur Springs	37.803315, 80.298700	Linoleum	40 SF	Assumed	11/30/2016	J. Sommers AI008854	Ritika Seal

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒

Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 3A (Greenbrier)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002330

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

WV License #: Please see attached.

Asbestos Inspection By: Please see attached.

Analysis By: Please see attached.

Lab: CEI Labs

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Harold Rumer

WV License #: AD003820

Air Monitor: Harold Rumer

WV License #: AA002509

Schedule:

Asbestos Removal:

Start Date: 12/08/2016

Completion Date: 1-4-17

Demo/Renovation:

Start Date: 12/08/2016

Completion Date: 02/28/17

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Area: Sq. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

ID #: WV042918 / WH13715

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

ID #: SMF-1032

Address: Rt. 2 Box 68

City: Bridgeport

State: WV

Zip Code: 26330

Contact Person: Kelli Sekela

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: _____

Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 3
ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-41	364 Freeland Avenue, White Sulphur Springs	37.80181, 80.29021	Mastic on Flashing	100 LF	Assumed	11/30/2016	J. Sommers AI008854	Sarah Talley
G-40	356 Freeland Avenue, White Sulphur Springs	37.80174, 80.29039	Linoleum	40 SF	Assumed	11/30/2016	J. Sommers AI008854	Mikaela Batta
G-39	309 Freeland Avenue, White Sulphur Springs	37.80190, 80.29087	Caulking	40 LF	Assumed	11/30/2016	J. Sommers AI008854	Candace Burrus
G-38	291 Freeland Avenue, White Sulphur Springs	37.80243, 80.29113	Caulking	64 LF	Assumed	11/30/2016	J. Sommers AI008854	Candace Burrus
G-37	265 Freeland Avenue, White Sulphur Springs	37.80266, 80.29113	Linoleum	400 SF	Assumed	11/30/2016	J. Sommers AI008854	Candace Burrus
G-36	252 Freeland Avenue, White Sulphur Springs	37.80264, 80.29082	Linoleum	20 SF	Assumed	11/30/2016	J. Sommers AI008854	Ritika Seal
G-35	246 Freeland Avenue, White Sulphur Springs	37.80247, 80.29068	Door Caulking	40 LF	Assumed	11/30/2016	J. Sommers AI008854	Ritika Seal
			Silver Roof Paint	800 SF	2%	12/21/2016	J. Sommers AI008854	Candace Burrus
G-34	235 Freeland Avenue, White Sulphur Springs	37.80241, 80.29067	Linoleum	42 SF	Assumed	11/30/2016	J. Sommers AI008854	Candace Burrus
G-33	213 Freeland Avenue, White Sulphur Springs	37.80216, 80.29053	Linoleum	32 SF	Assumed	11/30/2016	J. Sommers AI008854	Candace Burrus
G-26	43180 Midland Trail E., White Sulphur Springs	37.79778, 80.27879	Joint Compound	10 LF	Assumed	11/30/2016	J. Sommers AI008854	Mikaela Batta
G-53	43220 Midland Trail E., White Sulphur Springs	37.772901, -80.36035	Wiring	UK	Assumed	11/30/2016	J. Sommers AI008854	Mikaela Batta

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
Remediation Branch (31.62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Group 4A (Greenbrier) Address: City: County: Location Within Facility: Building Size (Sq. Ft.): Number of Floors: Age (Yrs): Present Use: Prior Use:	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. Lab: CEI Labs Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule: Asbestos Removal: Start Date: 12/08/2016 Completion Date: 1-4-17 Demo/Renovation: Start Date: 12/08/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Type(s):

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Pipes: Ln. Ft: % Asbestos:
Area: Sq. Ft: % Asbestos:
Other: Cu. Ft: % Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Zip Code: 26555

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV


Zip Code: 26330

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 01/04/17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 4

ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-29	182 Joe Belmont Road, Caldwell		Window Glazing	152 LF	3%	11/30/2016	J. Sommers AI008854	Candace Burrus
			Beige Linoleum	1000 SF	25%		J. Sommers AI008854	
			9"x9" Floor Tile & Mastic	140 SF	Assumed		J. Sommers AI008854	
G-3	185 2nd Street, Caldwell	37.780257, -80.392116	Linoleum	40 SF	Assumed	11/30/2016	J. Sommers AI008854	Mikaela Batta
G-20	558 Monroe Avenue, Ronceverte	37.74412, 80.47175	Black Tar	5 LF	Assumed	12/5/2016	J. Sommers AI008854	Sarah Talley
G-21	675 River Road, Ronceverte	37.719359, -80.499864	Black Tar Mastic around chimney	12 SF	Assumed	12/5/2016	J. Sommers AI008854	Ritika Seal
G-69	431 Fort Springs Pike, Ronceverte	37.74578, -80.54496	Window Glazing	112 LF	2%	12/13/2016	J. Sommers AI008854	Candace Burrus
			Mastic on Flashing	6 LF	Assumed			
G-55	260 Camp Ann Bailey, Caldwell	37.78238, -80.38704	Linoleum (bottom layer)	190 SF	25%	12/13/2016	J. Sommers AI008854	Shilpa Ladekar
			Mastic around Flashing	8 LF	Assumed			

WEST VIRGINIA



RECEIVED
JAN 09 2017

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Pesticides & Asbestos Programs
and Enforcement (3LC62)
EPA Region III

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification:		
Original <input checked="" type="checkbox"/>	Revision <input type="checkbox"/> (Highlight Changes)	Cancellation <input type="checkbox"/>
Type of Operation:		
Demolition <input checked="" type="checkbox"/>	Ordered Demolition <input type="checkbox"/>	Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>
Facility Owner:		
Name: West Virginia Homeland Security		
Address: 1900 Kanawha Blvd., E, EB80		
City: Charleston	State: WV	Zip Code: 25305
Contact Person: John Hoyer		Phone: (304) 389-7906
Facility Description:		
Name: Vacant Structures - Please see attached for Group 5A (Greenbrier)		
Address:		City:
County:	Location Within Facility:	
Building Size (Sq. Ft.):	Number of Floors:	Age (Yrs):
Present Use:	Prior Use:	
Asbestos Contractor:		
Name: Reclaim Company, LLC		Asbestos Contractor License #: AC002330
Address: P.O. Box 2162		
City: Fairmont	State: WV	Zip Code: 26555
Contact Person: Steve Gabbert		Phone: 304-366-7070
Other Contractor:		
Name: Reclaim Company, LLC		Contractor's License #: WV042918
Address: P.O. Box 2162		
City: Fairmont	State: WV	Zip Code: 26555
Contact Person: Steve Gabbert		Phone: 304-366-7070
Building Inspection:		
Inspection Date: Please see attached.		
Asbestos Inspection By: Please see attached.		WV License #: Please see attached.
Lab: CEI Labs		Analysis By: Please see attached.
Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy		
Is Asbestos Present at 1% or Greater:		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Project Designer: Harold Rumer		WV License #: AD003820
Air Monitor: Harold Rumer		WV License #: AA002509
Schedule:		
Asbestos Removal:	Start Date: 12/09/2016	Completion Date: 1-4-17
Demo/Renovation:	Start Date: 12/09/2016	Completion Date: 02/28/17
Project Work Hours: 7am to 5:30pm		Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)

Emergency Renovation: Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.																			
Demolition Ordered by Government Agency: Agency: _____ Name: _____ Title: _____ Date of Order: ___/___/___ Date Order to Begin: ___/___/___ (Copy of order must be attached.)																			
Types of ACM:																			
Asbestos Containing Material To Be Removed: <hr/> Type(s): Please see attached. <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;">Pipes:</td> <td style="width: 33%;">Ln. Ft:</td> <td style="width: 33%;">% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:	Cat. I & II Nonfriable ACM Not To Be Removed: <hr/> Type(s): _____ <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%;">Pipes:</td> <td style="width: 33%;">Ln. Ft:</td> <td style="width: 33%;">% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Description of planned demolition or renovation work and method(s) to be used: Wet methods for demolition and regulated site.																			
Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M): Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.																			
Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder: STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.																			
Waste Transporter: <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Name: Reclaim Company, LLC</td> <td style="width: 50%;">ID #: WV042918 / WH13715</td> </tr> <tr> <td>Address: P.O. Box 2162</td> <td></td> </tr> <tr> <td>City: Fairmont</td> <td>State: WV Zip Code: 26555</td> </tr> <tr> <td>Contact Person: Steve Gabbert</td> <td>Phone: 304-366-7070</td> </tr> </table>		Name: Reclaim Company, LLC	ID #: WV042918 / WH13715	Address: P.O. Box 2162		City: Fairmont	State: WV Zip Code: 26555	Contact Person: Steve Gabbert	Phone: 304-366-7070										
Name: Reclaim Company, LLC	ID #: WV042918 / WH13715																		
Address: P.O. Box 2162																			
City: Fairmont	State: WV Zip Code: 26555																		
Contact Person: Steve Gabbert	Phone: 304-366-7070																		
Waste Disposal Site: <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Name: Meadowfill Landfill</td> <td style="width: 50%;">ID #: SMF-1032</td> </tr> <tr> <td>Address: Rt. 2 Box 68</td> <td></td> </tr> <tr> <td>City: Bridgeport</td> <td>State: WV Zip Code: 26330</td> </tr> <tr> <td>Contact Person: Kelli Sekela</td> <td>Phone: 304-842-2784</td> </tr> </table>		Name: Meadowfill Landfill	ID #: SMF-1032	Address: Rt. 2 Box 68		City: Bridgeport	State: WV Zip Code: 26330	Contact Person: Kelli Sekela	Phone: 304-842-2784										
Name: Meadowfill Landfill	ID #: SMF-1032																		
Address: Rt. 2 Box 68																			
City: Bridgeport	State: WV Zip Code: 26330																		
Contact Person: Kelli Sekela	Phone: 304-842-2784																		
Certification: I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.																			
Signature of Owner/Operator: <u>Angela Mitchell</u> Date: <u>1</u> / <u>04</u> / <u>17</u>																			
Name and Title (Print or Type): Angela Mitchell, Contract Administrator																			



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 5

ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-22	1052 Anjean Road, Rupert	37.97223, 80.67572	Door Caulking	40 LF	Assumed	12/5/2016	J. Sommers AI008854	Ritika Seal
G-23	119 Feamster Road, Rupert	37.95822, 80.68323	Black Tar (under shingles)	1500 SF	5%	12/5/2016	J. Sommers AI008854	Sarah Talley
			Black Tar (around chimney)	5 LF	Assumed			
G-24	189 Front Street, Rupert	37.96453, 80.69833	Linoleum	110 SF	Assumed	12/5/2016	J. Sommers AI008854	Scott Maynard
G-5	4878 Midland Trail W., Charmco	37.780323, 80.384774	Vinyl Floor Tile	32 SF	2%	12/5/2016	J. Sommers AI008854	Ritika Seal
			12"x12" Floor Tile	32 SF	Assumed			
G-16	511 Riverside Drive, Rainelle	37.98970, 80.74742	Window Glazing	48 LF	2%	12/6/2016	J. Sommers AI008854	Candace Burrus
			Mastic on Flashing	10 LF	Assumed			
G-15	121 Riverside Drive, Rainelle	37.995107, 80.749226	White Floor Tile	120 SF	2%	12/6/2016	J. Sommers AI008854	Candace Burrus
			White Linoleum	40 SF	Assumed			
G-56	6972 Midland Trail W., Charmco	37.965185, -80.698525						
G-57	6834 Midland Trail W., Hines	37.98448, -80.72123	Black Mastic on house & chimney	25 LF	Assumed	12/15/2016	J. Sommers AI008854	Megan Rumble
G-70	141 Front St., Rupert	37.964032, -80.697243	Window Glazing	48 LF	Assumed	12/15/2016	J. Sommers AI008854	Samantha Card

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
and Enforcement Branch (SLC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: _____ Check No: _____
Postmark Date: _____ Paid By: _____
Notification No: _____ Amount: \$ _____

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>	
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>	
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description: Name: Vacant Structures - Please see attached for Special Group A (Greenbrier) Address: _____ City: _____ County: _____ Location Within Facility: _____ Building Size (Sq. Ft.): _____ Number of Floors: _____ Age (Yrs): _____ Present Use: _____ Prior Use: _____	
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. WV License #: Please see attached. Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule: Asbestos Removal: Start Date: 11/30/2016 Completion Date: 1-4-17 Demo/Renovation: Start Date: 11/30/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)	

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV


Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator:



Date: 01 / 04 / 17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Special Group
ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTOTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-51	115 Lower Pleasant Road, White Sulphur Springs	37.79861, 80.27952	12x12 Tile	136 SF	Assumed	11/22/2016	J. Frazier AI008690	Sarah Talley
G-4	35468 Midland Trail E., Caldwell	37.772605, -80.368054	Black Tar on Chimney	5 LF	Assumed	11/22/2016	J. Frazier AI008690	Daniel Liquori
G-2	132 2nd Street, Caldwell	37.779830, -80.392120	Black Tar on Flashing	UK	Assumed	11/22/2016	J. Frazier AI008690	Mikaela Batta
G-71	133 Back Alley Road, Caldwell	37.78048, -80.38951	Black Tar on Roof Shingles	1000 SF	5%	12/13/2016	J. Sommers AI008854	Samantha Card
			Mastic around Chimney	5 LF	Assumed			
G-72	43088 Midland Trail E., Caldwell	37.799279, -80.280312	Yellow Floor Tile	175 SF	3%	12/13/2016	J. Sommers AI008854	Shilpa Ladekar
			Window Glazing	88 LF	2%			
			Black Mastic around Chimney	10 LF	Assumed			

The seal of the State of West Virginia is circular. It features a central figure of a Native American holding a bow and arrow, with a plow behind him. The words "STATE OF WEST VIRGINIA" are inscribed around the top, and "MONTANI SEMPER LIBERI" around the bottom. Two stars are positioned on the left and right sides of the seal.

RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
Innovation Branch (3LC62)
EPA Region III

Operator Project No: 053-16

Date Rec'd:	Check No:
Postmark Date:	Paid By:
Notification No:	Amount: \$

Type of Notification: Original <input checked="" type="checkbox"/> Revision <input type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>		
Type of Operation: Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/> Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>		
Facility Owner: Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906		
Facility Description: Name: Vacant Structures - Please see attached for Group 6A (Greenbrier) Address: City: County: Location Within Facility: Building Size (Sq. Ft.): Number of Floors: Age (Yrs): Present Use: Prior Use:		
Asbestos Contractor: Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070		
Other Contractor: Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070		
Building Inspection: Inspection Date: Please see attached. Asbestos Inspection By: Please see attached. WV License #: Please see attached. Lab: CEI Labs Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509		
Schedule: Asbestos Removal: Start Date: 12/13/2016 Completion Date: 1-4-17 Demo/Renovation: Start Date: 12/13/2016 Completion Date: 02/28/17 Project Work Hours: 7am to 5:30pm Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)		

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: __/__/__ __:__ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: __/__/__

(Copy of order must be attached.)

Title:

Date Order to Begin: __/__/__

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Phone: 304-366-7070

Zip Code: 26555

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032

State: WV

Phone: 304-842-2784

Zip Code: 26330

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 1/04/17

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Greenbrier County, WV - Group 6

ABATEMENT ALL COMPLETE

SITE	ADDRESS	GPS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSOTILE	INSPECTION DATE	INSPECTOR	ANALYST
G-11	156 9th Street, Rainelle	37.97338, 80.76256	Mastic around roof vents	5 LF	Assumed	12/6/2016	J. Sommers AI008854	Candace Burrus
G-10	117 9th Street, Rainelle	37.97360, 80.76271	Mastic around chimney	5 LF	Assumed	12/6/2016	J. Sommers AI008854	Shilpa Ladekar
G-8	137 7th Street, Rainelle	37.97344, 80.76452	Window Glazing	8 LF	2%	12/6/2016	J. Sommers AI008854	Megan Fisher
			Linoleum	35 SF	Assumed			
G-7	121 4th Street, Rainelle	37.97097, 80.76516	9"x9" Floor Tile	30 SF	Assumed	12/6/2016	J. Sommers AI008854	Megan Fisher
G-18	505 Virginia Avenue, Rainelle	37.96586, 80.77013	Linoleum	42 SF	Assumed	12/6/2016	J. Sommers AI008854	Candace Burrus
G-14	106 Kentucky Avenue, Rainelle	37.96616, 80.77130	Mastic around roof vents	4 LF	Assumed	12/6/2016	J. Sommers AI008854	Samantha Card
G-19	Lot 1 Kentucky Avenue, Rainelle	37.96541, 80.77129	Gray Sheet Vinyl	700 SF	25%	12/6/2016	J. Sommers AI008854	Samantha Card
			Mastic around roof vents	4 LF	Assumed			
G-13	505 James River Kanawha Turnpike, Rainelle	37.96771, 80.75962	Mastic around roof vents	10 LF	Assumed	12/6/2016	J. Sommers AI008854	Mikaela Batta
			Window Glazing	48 LF	2%			
G-9	484 8th Street, Rainelle	37.96937, 80.75969	Stair Treads	32 SF	Assumed	12/6/2016	J. Sommers AI008854	Mikaela Batta
G-17	388 Surbaugh Avenue, Rainelle	37.97181, 80.76030	Mastic around chimney	5 LF	Assumed	12/6/2016	J. Sommers AI008854	Samantha Card
G-12	323 Greenbrier Avenue, Rainelle	37.97072, 80.76083	None Detected	N/A	N/A	12/6/2016	J. Sommers AI008854	Mikaela Batta
G-58	121 3rd St., Rainelle	37.969514, -80.764815	Transite Siding	2000 SF	15%	12/14/2016	J. Sommers AI008854	Mikaela Batta
			Mastic on Chimney	8 LF	Assumed			
G-59	426 6th St., Rainelle	37.96936, -80.76172	Window Glazing	96 LF	2%	12/14/2016	J. Sommers AI008854	Mikaela Batta
			Mastic around chimney	6 LF	Assumed			
G-60	230 7th St., Rainelle	37.97238, -80.76349	Window Glazing	112 LF	2%	12/14/2016	J. Sommers AI008854	Mikaela Batta
			Black Tar (on shingles)	120 SF	2%			
			Shingles	120 SF	2%			
			Mastic on Chimney	8 LF	Assumed			
G-61	236 7th St., Rainelle	37.972171, -80.763562	Electrical Wiring	UK	Assumed	12/14/2016	J. Sommers AI008854	Ryan Williams
G-62	207 9th St., Rainelle	37.97269, -80.76194	Floor Tile (Sheet Vinyl)	120 SF	25%	12/14/2016	J. Sommers AI008854	Mikaela Batta
			Mastic on chimney	6 LF	Assumed			
G-63	336 9th St., Rainelle	37.97126, -80.76046	Window Glazing	80 LF	3%	12/14/2016	J. Sommers AI008854	Mikaela Batta
			Electrical Wiring	UK	Assumed			
G-64	121 Greenbrier Ave., Rainelle	37.96901, -80.76400	Window Glazing	48 LF	Assumed	12/14/2016	J. Sommers AI008854	Mikaela Batta
G-65	705 Horton Ave., Rainelle	37.97286, -80.76360	Window Glazing	80 LF	Assumed	12/14/2016	J. Sommers AI008854	Megan Rumble
			Tan Linoleum	70 SF	25%			
G-66	255 James River-Kanawha Turpike, Rainelle	37.96880, -80.76452	Cream Linoleum	260 SF	25%	12/14/2016	J. Sommers AI008854	Samantha Card
			Blue/Green Linoleum	64 SF	25%			
			White Pipe Wrap	50 LF	65%			
			Mastic on chimney	5 LF				
G-68	607 Main St., Rainelle	37.97257, -80.76063	Shingles	12 SF	Assumed	12/14/2016	J. Sommers AI008854	Mikaela Batta
G-74	616 Center St. E., Rainelle	37.973810, -80.760104	Mastic on Roof Vents	6 LF	Assumed	12/15/2016	J. Sommers AI008854	Samantha Card
G-76	150 Greenbrier Ave., Rainelle	37.969146, -80.763425	Roof Paint	520 SF	2%	12/14/2016	J. Sommers AI008854	Mikaela Batta
			Door Caulking	40 LF	Assumed			

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
and Enforcement Branch (3LC62)

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION

Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd:

Check No:

Postmark Date:

Paid By:

Notification No:

Amount: \$

Type of Notification:

Original ☒

Revision ☐ (Highlight Changes)

Cancellation ☐

Type of Operation:

Demolition ☒

Ordered Demolition ☐

Renovation ☐

Emergency Renovation ☐

Facility Owner:

Name: West Virginia Homeland Security

Address: 1900 Kanawha Blvd., E, EB80

City: Charleston

State: WV

Zip Code: 25305

Contact Person: John Hoyer

Phone: (304) 389-7906

Facility Description:

Name: Vacant Structures - Please see attached for Group 1 (Roane County)

Address:

City:

County:

Location Within Facility:

Building Size (Sq. Ft.):

Number of Floors:

Age (Yrs):

Present Use:

Prior Use:

Asbestos Contractor:

Name: Reclaim Company, LLC

Asbestos Contractor License #: AC002330

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Other Contractor:

Name: Reclaim Company, LLC

Contractor's License #: WV042918

Address: P.O. Box 2162

City: Fairmont

State: WV

Zip Code: 26555

Contact Person: Steve Gabbert

Phone: 304-366-7070

Building Inspection:

Inspection Date: Please see attached.

Asbestos Inspection By: See attached

WV License #: See attached

Lab: CEI Labs

Analysis By: Please see attached.

Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy

Is Asbestos Present at 1% or Greater:

Yes ☒ No ☐

Project Designer: Harold Rumer

WV License #: AD003820

Air Monitor: Harold Rumer

WV License #: AA002509

Schedule:

Asbestos Removal:

Start Date: 01/04/2017

Completion Date: 01/31/2017

Demo/Renovation:

Start Date: 01/04/2017

Completion Date: 01/31/2017

Project Work Hours: 7am to 5:30pm

Work Days: M ☒ Tu ☒ W ☒ Th ☒ F ☒ Sa ☒ Su ☐ (Check)

Emergency Renovation:

Date & Hour of Sudden Unexpected Event: ___/___/___ :___ AM PM

Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.

Demolition Ordered by Government Agency:

Agency:

Name:

Date of Order: ___/___/___

(Copy of order must be attached.)

Title:

Date Order to Begin: ___/___/___

Types of ACM:

Asbestos Containing Material To Be Removed:

Cat. I & II Nonfriable ACM Not To Be Removed:

Type(s): Please see attached.

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Type(s):

Pipes:	Ln. Ft:	% Asbestos:
Area:	Sq. Ft:	% Asbestos:
Other:	Cu. Ft:	% Asbestos:

Description of planned demolition or renovation work and method(s) to be used:

Wet methods for demolition and regulated site.

Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M):

Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.

Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder:

STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.

Waste Transporter:

Name: Reclaim Company, LLC

Address: P.O. Box 2162

City: Fairmont

Contact Person: Steve Gabbert

ID #: WV042918 / WH13715

State: WV

Zip Code: 26555

Phone: 304-366-7070

Waste Disposal Site:

Name: Meadowfill Landfill

Address: Rt. 2 Box 68

City: Bridgeport

Contact Person: Kelli Sekela

ID #: SMF-1032


State: WV

Zip Code: 26330

Phone: 304-842-2784

Certification:

I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct.

Signature of Owner/Operator: 

Date: 01 / 04 / 16

Name and Title (Print or Type): Angela Mitchell, Contract Administrator



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Roane County, WV - Group 1

SITE	ADDRESS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	INSPECTOR	ANALYST
R-005	30 Youngs Trailer Court	Black Tar Right/Front Side	12 LF	Assumed	12/16/2016	J. Frazier AI008690	Ryan Williams
R-006	58 Youngs Court	Black Tar on Roof Vents	5 SF	Assumed	12/16/2016	J. Frazier AI008690	Ryan Williams
R-007	26 Youngs Trailer Court	Silver Paint Main Roof	720 SF	3%	12/16/2016	J. Frazier AI008690	Ryan Williams
		Black Tar on Roof Vents	7 SF	Assumed			
R-008	61 Youngs Court						
R-011	63 Youngs Court	Black Tar on Roof Vents	5 SF	Assumed	12/16/2016	J. Frazier AI008690	Taylor B. Metcalf

WEST VIRGINIA



RECEIVED
JAN 09 2017

Pesticides & Asbestos Programs
Enforcement Branch (3LC62)
EPA Region III

NOTIFICATION OF ABATEMENT, DEMOLITION, OR RENOVATION


Date: 1/4/17

Operator Project No: 053-16

OFFICE USE ONLY

Date Rec'd: Check No:
Postmark Date: Paid By:
Notification No: Amount: \$

Type of Notification:	
Original <input type="checkbox"/>	Revision <input checked="" type="checkbox"/> (Highlight Changes) Cancellation <input type="checkbox"/>
Type of Operation:	
Demolition <input checked="" type="checkbox"/> Ordered Demolition <input type="checkbox"/>	Renovation <input type="checkbox"/> Emergency Renovation <input type="checkbox"/>
Facility Owner:	
Name: West Virginia Homeland Security Address: 1900 Kanawha Blvd., E, EB80 City: Charleston State: WV Zip Code: 25305 Contact Person: John Hoyer Phone: (304) 389-7906	
Facility Description:	
Name: Vacant Structures - Please see attached for Group 1 (Roane County) Address: City: County: Location Within Facility: Building Size (Sq. Ft.): Number of Floors: Age (Yrs): Present Use: Prior Use:	
Asbestos Contractor:	
Name: Reclaim Company, LLC Asbestos Contractor License #: AC002330 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Other Contractor:	
Name: Reclaim Company, LLC Contractor's License #: WV042918 Address: P.O. Box 2162 City: Fairmont State: WV Zip Code: 26555 Contact Person: Steve Gabbert Phone: 304-366-7070	
Building Inspection:	
Inspection Date: Please see attached. Asbestos Inspection By: See attached Lab: CEI Labs WV License #: See attached Analysis By: Please see attached. Procedure Used to Detect Presence of Asbestos: Polarized Light Microscopy Is Asbestos Present at 1% or Greater: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Project Designer: Harold Rumer WV License #: AD003820 Air Monitor: Harold Rumer WV License #: AA002509	
Schedule:	
Asbestos Removal: Start Date: 01/04/2017 Completion Date: 01/31/2017	
Demo/Renovation: Start Date: 01/04/2017 Completion Date: 01/31/2017	
Project Work Hours: 7am to 5:30pm	Work Days: M <input checked="" type="checkbox"/> Tu <input checked="" type="checkbox"/> W <input checked="" type="checkbox"/> Th <input checked="" type="checkbox"/> F <input checked="" type="checkbox"/> Sa <input checked="" type="checkbox"/> Su <input type="checkbox"/> (Check)

Emergency Renovation: Date & Hour of Sudden Unexpected Event: ____/____/____ :____ AM PM Attach a description of the sudden, unexpected event and how this results in an unsafe condition, would cause equipment damage or an unreasonable financial burden.																			
Demolition Ordered by Government Agency: Agency: _____ Name: _____ Title: _____ Date of Order: ____/____/____ Date Order to Begin: ____/____/____ (Copy of order must be attached.)																			
Types of ACM:																			
Asbestos Containing Material To Be Removed: <hr/> Type(s): Please see attached. <table style="width: 100%;"> <tr> <td>Pipes:</td> <td>Ln. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:	Cat. I & II Nonfriable ACM Not To Be Removed: <hr/> Type(s): <table style="width: 100%;"> <tr> <td>Pipes:</td> <td>Ln. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Area:</td> <td>Sq. Ft:</td> <td>% Asbestos:</td> </tr> <tr> <td>Other:</td> <td>Cu. Ft:</td> <td>% Asbestos:</td> </tr> </table>	Pipes:	Ln. Ft:	% Asbestos:	Area:	Sq. Ft:	% Asbestos:	Other:	Cu. Ft:	% Asbestos:
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Pipes:	Ln. Ft:	% Asbestos:																	
Area:	Sq. Ft:	% Asbestos:																	
Other:	Cu. Ft:	% Asbestos:																	
Description of planned demolition or renovation work and method(s) to be used: Wet methods for demolition and regulated site.																			
Description of procedures to be used to comply with NESHAP (40CFR61 Subpart M): Regulated area, wet methods for removal, air tight disposal containers, and double 6 mil poly plastic for a total of 12 mil.																			
Description of procedures to be followed in the event that unexpected asbestos is found or previously nonfriable ACM becomes crumbled, pulverized, or reduced to powder: STOP ALL WORK. Identify the ACM, develop an abatement procedure, and notify all applicable government agencies.																			
Waste Transporter: <table style="width: 100%;"> <tr> <td>Name: Reclaim Company, LLC</td> <td>ID #: WV042918 / WH13715</td> </tr> <tr> <td>Address: P.O. Box 2162</td> <td></td> </tr> <tr> <td>City: Fairmont</td> <td>State: WV Zip Code: 26555</td> </tr> <tr> <td>Contact Person: Steve Gabbert</td> <td>Phone: 304-366-7070</td> </tr> </table>		Name: Reclaim Company, LLC	ID #: WV042918 / WH13715	Address: P.O. Box 2162		City: Fairmont	State: WV Zip Code: 26555	Contact Person: Steve Gabbert	Phone: 304-366-7070										
Name: Reclaim Company, LLC	ID #: WV042918 / WH13715																		
Address: P.O. Box 2162																			
City: Fairmont	State: WV Zip Code: 26555																		
Contact Person: Steve Gabbert	Phone: 304-366-7070																		
Waste Disposal Site: <table style="width: 100%;"> <tr> <td>Name: Meadowfill Landfill</td> <td>ID #: SMF-1032</td> </tr> <tr> <td>Address: Rt. 2 Box 68</td> <td></td> </tr> <tr> <td>City: Bridgeport</td> <td>State: WV Zip Code: 26330</td> </tr> <tr> <td>Contact Person: Kelli Sekela</td> <td>Phone: 304-842-2784</td> </tr> </table>		Name: Meadowfill Landfill	ID #: SMF-1032	Address: Rt. 2 Box 68		City: Bridgeport	State: WV Zip Code: 26330	Contact Person: Kelli Sekela	Phone: 304-842-2784										
Name: Meadowfill Landfill	ID #: SMF-1032																		
Address: Rt. 2 Box 68																			
City: Bridgeport	State: WV Zip Code: 26330																		
Contact Person: Kelli Sekela	Phone: 304-842-2784																		
Certification: I certify that an individual trained in the provisions of 40 CFR 61, Subpart M will be on site during the demolition or renovation and evidence that the required training has been accomplished by the person will be available for inspection during normal business hours. I further certify that the information contained in the notification is correct. Signature of Owner/Operator: <u></u> Date: <u>01</u> / <u>04</u> / <u>16</u> Name and Title (Print or Type): <u>Angela Mitchell, Contract Administrator</u>																			



WVHSEM / FEMA
June 23rd Flood Cleanup Project
Roane County, WV - Group 1

SITE	ADDRESS	ASBESTOS TO BE REMOVED	APPROX. SIZE	CHRYSTILE	INSPECTION DATE	INSPECTOR	ANALYST
R-005	30 Youngs Trailer Court	Black Tar Right/Front Side	12 LF	Assumed	12/16/2016	J. Frazier AI008690	Ryan Williams
R-006	58 Youngs Court	Black Tar on Roof Vents	5 SF	Assumed	12/16/2016	J. Frazier AI008690	Ryan Williams
R-007	26 Youngs Trailer Court	Silver Paint Main Roof	720 SF	3%	12/16/2016	J. Frazier AI008690	Ryan Williams
		Black Tar on Roof Vents	7 SF	Assumed			
R-008	61 Youngs Court	Black Tar on Roof Vents	5 SF	Assumed	12/16/2016	J. Frazier AI008690	Ritika Seal
R-011	63 Youngs Court	Black Tar on Roof Vents	5 SF	Assumed	12/16/2016	J. Frazier AI008690	Taylor B. Metcalf

P.O. Box 2162
Fairmont, WV
26555



1000



19103

U.S. POSTAGE
PAID
FAIRMONT, WV
26554
JAN 04, 17
AMOUNT

\$2.83

R2305K143193-06

**Attention: Asbestos Coordinator(3WC32)
U.S. Environmental Protection Agency
Region III
1650 Arch Street
Philadelphia, PA 19103-2029**

